

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7



Results of ASTM B 117 Salt Spray Test  
# of Nail Heads Showing Red Rust




FIG. 8

Results of Driven Fastener ASTM B 117 Salt Spray Test  
# of Nail Heads Showing Red Rust




FIG. 9